

RECEIVED

JAN 08 2001

DIVISION OF  
OIL, GAS AND MINING

FORM MR-AR  
(Revised 3/98)

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/00 To (mo./yr.) 12/00
2. DOGM File Number (Mine No): 1 5530065
3. Mine Name: SNOW WHITE
4. Mineral(s) Mined (or permitted to mine): marble
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
1/4, 1/4, SE 1/4, Section 9, Township 39S, Range 19W  
1/4, 1/4, 1/4, Section, Township, Range  
1/4, 1/4, 1/4, Section, Township, Range
7. Name of Operator or Company: COLOR COUNTRY ROCK LLC
8. Permanent Street Address: 291 East 1400 South, Suite #1  
City, State, Zip: St. George, UT 84790  
Phone: (435) 656-5763 Fax: \_\_\_\_\_
9. Company Representative (or designated operator):  
Name: Preston L. Hafen  
Title: Partner  
Business Address: 115 South Main  
City, State, Zip: Vernal, UT 84782  
Phone: (435) 574-2760 Fax: (435) 574-2760  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? 50 TONS ✓

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

old road utilized, 100 Tons of material  
blasted, 50 Tons of broken rock mined  
3 areas blasted approx 150' x 100' x 3 =  
45,000 Ft<sup>2</sup> (approximately 1 acre)

5. How much additional acreage was disturbed during the past year? 10' x 200' = 2,000 Ft<sup>2</sup> road

6. How much acreage was reclaimed during the past year? NONE

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Broken rock remains to be removed from all  
3 areas worked - reclamation will include  
smoothing surface, backfilling w/ soil & seeding  
where applicable after broken rock has been mined

8. What is the total disturbed acreage of entire project at years end? < 2 acres

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Remove broken rock from 3 blasted areas.  
Smooth surface, Extend mining in 3 areas.  
Back fill with soil and reseed where  
applicable - Reclamation will completed on a  
continuing basis as mining is completed.

**NOTE:**

Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Title of Operator:

Signature of Operator:

Date:

Preston L. Hafen  
Partner  
Preston L. Hafen  
01/05/01

jb  
a:\forms\MR-AR